



PRESENTATION ON KZN COGTA PERIODIC EVALUATIONS


DPME: EVALUATION SEMINAR

Department: Cooperative Governence and Traditional Affairs PROVINCE OF KWAZULU-NATAL

WHY EVALUATE

freshspectrum.com





I can't tell you how valuable your program is

I can








Evaluator


EVALUATION CYCLE





QUARTERLY EVALUATIONS






 General challenges in this area related to projects not being implemented in time and scope.

All projects had project steering committees, a question is raised as to how the constituency of these structures ensured smooth implementation of these projects and ensured that implementation bottlenecks were addressed.





 There were different perspectives of the support application, with the Department feeling that the process is efficient and the municipalities feeling that the process does not respond to project needs.











If feasibility studies are conducted and subsequent designs are developed, why are projects implemented out of budget and out of scope? This is asked as a result of the fact that projects experienced deviated deliverable costs.

 A majority of projects experienced deviated costs per deliverables. The majority of projects which experienced expenditure challenges were projects were found under Massification Support programme.

 The lower than expected functional facilities and end user percentages indicate that deliverables were not produced on time due resource and implementation challenges.





 While the majority of the projects were economical, efficiency challenges such as time and scope management affected the deliverables leading to the noted results.





WARD 2 GALLERY



COGTA Field Workers talking to project beneficiaries on site

F

EXTERIOR :ABLUTION FACILITIES FUNDED BY COGTA

Evaluation of ablution facilities project in NDZ Municipality



INTERIOR :ABLUTION FACILITIES FUNDED BY COGTA



OUTSIDE SINK AND ITS PLUMBING



ABLUTION FACILITY BENEFITING COMMUNITIES



LEAKING TOILETS IN WARD 2



COMMUNITY TRYING
MANAGE LEAKING TOILETS IN
WARD 2



INCORRECTLY INSTALLED TOILET SEAT WHICH LEADS TO WATER LEAKS



POOR PUMBLING RESULTING TO WATER LEAKS



CRACKED CEMENT SINK WHICH WILL EVENTUALLY FALL

TAP STARTING TO COME OFF DUE TO POOR INSTALLATION

WARD 3 GALLERY

COGTA FIELD WORKERS IN WARD 3



COGTA FIELD WORKERS JOINED BY THE MAYOR IN WARD 3



WHEN IN RAIN



ABLUTION FACILITY FLUSHING HANDLE NOT COMING UP **RESULTTING TO WASTE OF WATER**



DRAINAGE SYSTEM DAMAGED SINCE IT IS **INCORRECTLY INSTALLED ON** THE STREET



POOR SINK PIPING UNDER THE SINK WHICH RESULTS TO **BLOCKAGES**



BROKEN DRAINAGE SYSTEM



TOILET TOP PART WHICH DOES NOT OPEN WHEN THE USERS DO NOT HAVE WATER



FACILITIES' ROOF AT RISK TO BE **BLOWN BY WIND**



TOILET PAPER HOLDER NOT OPENING THEREFORE CAN'T BE **USED**



MIDTERM REVIEW





Department: Cooperative Governence and Traditional Affairs PROVINCE OF KWAZULU-NATAL

MIDTERM REVIEW

IMPACT: STRATEGIC GOALS

OUTCOMES: STRATEGIC OBJECTIVES


IMMEDIATE OUTCOMES: STRATEGIC INTERVENTIONS


PLANNED OUTPUTS: FIVE-YEAR TARGET:

ACTIVITIES: DEPARTMENTAL ACTIONS

INPUTS: APP INDICATORS

PROGRAMME 2: ASSESSMENT OF ALIGNMENT LOGIC MODEL





supported

with the IGR

Framework

identified/aligned

projects

10





END

THANK YOU